



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

First Named Patentee : Peter Crane et al.

Appln. No. : 09/808,843

Filed : March 15, 2001

Title : Micro-Actuator Structure for Improved Stability

Patent No. : 6,851,120 B2

Issued : February 1, 2005

Docket No. : I 69.12-0487

Certificate
JUN 24 2005
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner For Patents
P.O. Box 1450
Alexandria, VA 22313-1450

I CERTIFY THAT THIS PAPER IS BEING SENT BY U.S. MAIL,
FIRST CLASS, TO THE ASSISTANT COMMISSIONER FOR
PATENTS, ALEXANDRIA, VA 22313, THIS 16th DAY OF

June, 2005

David Michael

PATENT ATTORNEY

In conformity with the notice appearing in the May 6, 1969 Official Gazette,
Applicant requests a Certificate of Correction in connection with the above-identified patent.

Form PTO-SB/44 entitled CERTIFICATE OF CORRECTION setting out the errors
has been completed and is enclosed. Applicant respectfully requests that the enclosed Certificate
be approved and signed by an Attesting Officer, and that a copy be returned to Applicant's attorney
for attachment to the original Certificate of Letters Patent.

All of the errors requested to be corrected appear to have occurred in the printing of
the patent, therefore no fee is required.

JUN 27 2005

The Commissioner is authorized to charge any additional fees associated with this communication or credit any overpayment to Deposit Account 11-0982. A duplicate of this communication is enclosed.

Respectfully submitted,

KINNEY & LANGE, P.A.

By: Dina M. Khaled

Dina M. Khaled, Reg. No. 52,761
THE KINNEY & LANGE BUILDING
312 South Third Street
Minneapolis, MN 55415-1002
Telephone: (612) 339-1863
Fax: (612) 339-6580

DMK:dab

JUN 27 2005

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**PATENT NO. : 6,851,120 *B2*Page 1 of 1

APPLICATION NO.: 09/808,843

ISSUE DATE : February 1, 2005

INVENTOR(S) : Peter Crane et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4

Line 16, delete "finally", insert --finely--

Column 5

Line 64, delete "micro actuator", insert --microactuator--

Column 5

Line 66, delete "inability", insert --ability--

Column 5

Lines 67-68, delete "micro actuator", insert --microactuator--

Column 8

Line 25, delete "bean-i", insert --beam--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Dina M. Khaled, Kinney & Lange PA
312 South Third Street
Minneapolis, MN 55415-1002

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.